




### SPF3-1500 Repair Kit

- (1) Pilot Cage Unit Part Number 5060
- (1) Temperature Controller Part Number 2784
- (1) Pilot Cage Unit Gasket Part Number 2394
- (1) Liner Valve Gasket Part Number 2352
- (1) Liner Valve Assembly Part Number 1709
- (1) Temperature Controller Gasket Part Number 2362
- (1) Main Cover Gasket Part Number 2386
- (1) Piston Cover Gasket Part Number 2387
- (1) Liner Locknut Gasket Part Number 2385
- (1) Liner Lock Nut Part Number 1822
- (1) Liner Lock Nut Screw Part Number 1557



\*Tool required for repair:  
Liner Valve Removal Tool Part Number L99050